



601 McCarthy Blvd., Milpitas, CA 95035
(408) 801-1000 Fax (408) 801-8657

Product Change Notification Form

PCN #: 54-34-00013

Rev: 1

Issue Date: July 18, 2007

Type of Change: Firmware Revision

Detailed Description of Change: This notification is to inform you on a new firmware release 2.13 for SSD UATA 5000 1.8", New firmware improves SSD performance;

Table below provides the list of differences.

Parameter	Firmware revision 1.26	Firmware revision 2.13
Sequential Read ^{2,3}	62MB/s	67MB/s
Sequential Write ^{2,3}	36MB/s	47MB/s
Random Read (512B) ^{1,3}	7000	7430

1. IOMETER 2003.12.16
2. H2BENCH.c,v 3.6 2002/10/31, Windows 32-bit
3. Tested in Ultra DMA 5

Reason for change:

Product being updated with newer firmware which provides higher performance.

Products affected:

Part Number	Description
SDU5B-032G-000000	Firmware update revision 2.13

Availability:

Milestone	Date
First Availability of Post-Conversion Product (*) - 32GB	7/25/2007

(*) The date of "First Availability of Post-Conversion Product" is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand; therefore, although customers should be prepared to receive the Post-Converted Products on this date, we will continue to ship the pre-converted products until the inventory has been depleted.

Impact of Change and Recommended Action:

New firmware improves the performance of the SSD UATA 5000 1.8" product.

Reference Documents / Attachments:

SanDisk SSD UATA 5000 1 8 Datasheet
Should you have any issues with the timeline or content of this change, please contact the Representative listed below within 30 days. No response will be deemed as customer's acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this PCN.

Contacts:	Name	Email
Product Management	Eyal bek	Eyal.bek@sandisk.com